Technical Report CERC-95-16 October 1995



US Army Corps of Engineers

Waterways Experiment Station

# Ofu Harbor, American Samoa, Breakwater 2-D Hydraulic Stability Test

by George F. Turk



Approved For Public Release; Distribution is Unlimited

19960212 250

The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products.


# Ofu Harbor, American Samoa, Breakwater 2-D Hydraulic Stability Test

by George F. Turk

U.S. Army Corps of Engineers Waterways Experiment Station 3909 Halls Ferry Road Vicksburg, MS 39180-6199

Final report

Approved for public release; distribution is unlimited



#### Waterways Experiment Station Cataloging-in-Publication Data

Turk, George F.

Ofu Harbor, American Samoa, breakwater 2-D hydraulic stability test / by George F. Turk; prepared for U.S. Army Engineer Division, Pacific Ocean.

36 p.: ill.; 28 cm. — (Technical report; CERC-95-16) Includes bibliographic references.

1. Breakwaters — American Samoa — Ofu Harbor. 2. Harbors — American Samoa — Ofu. I. United States. Army. Corps of Engineers. Pacific Ocean Division. II. U.S. Army Engineer Waterways Experiment Station. III. Coastal Engineering Research Center (U.S. Army Engineer Waterways Experiment Station) IV. Title. V. Series: Technical report (U.S. Army Engineer Waterways Experiment Station); CERC-95-16. TA7 W34 no.CERC-95-16

# **Contents**

Preface		 	 	 . v
1-Introduction		 	 	 . 1
The Prototype		 	 	 1
2—Test Model		 	 	 . 2
Scaling of the Model		 	 	 . 4
3—Test Results	• (	 	 	 11
Data Acquisition		 	 	 11
Determination		 	 	 19 20
4—Conclusions and Comments		 	 	 22
References			 	 24
Appendix A: Photographs of Ofu Breakwater 2-D Stability Tests		 	 	 <b>A</b> 1
SF298				
List of Figures				
Figure 1. Flume layout				
Figure 2. Breakwater configuration				
Figure 3. Of u breakwater alignment between Sta. 4+00 an				
		-		 _

Figure 4.	4.1-tonne tribar			
Figure 5.	Thirty-percent porosity block used for underlayer 9			
Figure 6.	Rib cap configuration of Ofu breakwater			
Figure 7.	Wave heights as a function of board stroke, $T = 9 \text{ sec} \dots 12$			
Figure 8.	Wave heights as a function of board stroke, $T = 11 \text{ sec} \dots 13$			
Figure 9.	Wave heights as a function of board stroke, $T = 13 \text{ sec} \dots 13$			
Figure 10.	Wave heights as a function of board stroke, $T = 15 \text{ sec}$ 14			
Figure 11.	Wave heights as a function of board stroke, $T = 17 \text{ sec}$ 14			
Figure 12.	Wave heights as a function of board stroke, $T = 18 \text{ sec}$ 15			
Figure 13.	Wave heights as a function of board stroke, $T = 20 \text{ sec}$ 15			
Figure 14.	Maximum attainable wave height on reef at structure toe 17			
Figure 15.	Wave transformation on reef for $T = 15$ sec			
Figure 16.	Wave transformation on reef for $T = 17 \text{ sec} \dots 18$			
Figure 17.	Wave transformation on reef for $T = 18$ sec			
Figure 18.	Wave transformation on reef for $T = 20 \text{ sec} \dots 19$			
Figure A1.	Model of Ofu breakwater			
Figure A2.	Trough of short-period wave $(T = 9 \text{ sec})$ passing over reef A2			
Figure A3.	Short-period wave $(T = 11 \text{ sec})$ breaking on reef			
Figure A4.	Wave $(T = 17 \text{ sec})$ breaking on structure			
Figure A5.	Wave $(T = 18 \text{ sec})$ breaking on structure			
List of	lables			
Table 1.	Model-Prototype Scale Relations (1:23 scale)			
Table 2.	Prototype and Model Material Sizes			
Table 3.	Stability Test Wave Conditions			
Table 4.	Summary of 2-D Stability Tests for 4.1-tonne Tribars 21			

### **Preface**

The two-dimensional physical model investigation of the Ofu breakwater, American Samoa, described in this report was requested by the U.S. Army Engineer Division, Pacific Ocean (POD) and conducted at the Coastal Engineering Research Center (CERC) of the U.S. Army Engineer Waterways Experiment Station (WES). Authorization for WES to perform the study was granted by POD in Intra-Army Order E9640008 dated 28 December 1993, which was subsequently approved by Headquarters, U.S. Army Corps of Engineers. Funds for model testing were authorized by POD on 27 December 1993 and 24 January 1994.

Model tests were conducted at WES during January 1994 by personnel of the Wave Research Branch (WRB) of the Wave Dynamics Division (WDD), CERC, under the direction of Dr. James R. Houston and Mr. Charles C. Calhoun, Jr., Director and Assistant Director of CERC, respectively; and the direct guidance of Messrs. C. E. Chatham, Jr., Chief of WDD; and Mr. D.D. Davidson, Chief of WRB. Tests were conducted by Messrs. George F. Turk, Research Hydraulic Engineer; C. Ray Herrington, Civil Engineering Technician; Johnny Heggins, Civil Engineering Technician; and David Daily of the WES Instrumentation Services Division. This report was prepared by Mr. Turk, with a special thanks to Messrs. Jeffrey A. Melby and Ernest R. Smith, CERC.

Liaison was maintained with POD through telephone conversations and facsimile transmission during the course of the investigation. The POD Point of Contact was Mr. Pat Tom, who provided cross-sectional and underlayer block designs.

At the time of publication of this report, Director of WES was Dr. Robert W. Whalin. Commander of WES was COL Bruce K. Howard, EN.

The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products.

# 1 Introduction

#### The Prototype

Ofu Harbor is located on the island of Ofu, American Samoa, in the South Pacific, approximately 3,700 km southeast of the Hawaiian Islands. The island has a volcanic origin, and is protected by numerous large coral reefs. The harbor and protecting stone rubble-mound breakwater were originally constructed in 1975.

#### The Problem

In 1981 the Ofu breakwater was severely damaged by tropical storm Esau, with subsequent repairs completed in 1992. Then in 1990, Hurricane Ofa struck American Samoa and the breakwater again sustained severe damage. Before the breakwater could be rehabilitated, Hurricane Val further damaged the structure in 1991. Currently the breakwater is almost completely destroyed. Armoring and underlayers on both the harbor and sea sides require complete repair. The entrance channel and turning basin require dredging to remove stone and dredged material washed into the harbor.

#### **Purpose of Study**

At the request of the U.S. Army Engineer Division, Pacific Ocean (POD), two-dimensional (2-D) wave tests were conducted at the U.S. Army Engineer Waterways Experiment Station (WES) Coastal Engineering Research Center (CERC) to determine the stability of selected concrete armor units when placed on concrete revetment blocks and subjected to a design condition of a 17-sec, 3.47-m (11.4-ft) wave. The proposed breakwater consisted of 4.1-tonne (4.5-U.S.-ton) tribar armor units, placed on an underlayer of 1.45-tonne (1.6-U.S.-ton) 30-percent porosity blocks, secured at the crown transition with a concrete rib cap.

# 2 Test Model

#### Scaling of the Model

Two-dimensional stability tests were conducted at a geometrically undissorted linear scale of 1:23, model to prototype. Scale was based on size availability of model tribars and the capabilities of the available wave generator to produce required wave heights at modeled water depths. Time relations were scaled according to Froude Model Law (Stevens et al. 1942). Model to prototype relations were derived in terms of length l and time t shown in Table 1.

Table 1 Model-Prototype Scale Relations (1:23 scale)					
Characteristic	Dimension	Scale Relations Model:Prototype			
Length	1	i,= 1:23			
Area	/ <sup>2</sup>	a, = 1:529			
Volume	/³	v, = 1:12,167			
Time	112	t, = 1:4.8			

The specific weight of water used in the model was 1,002 kg/m<sup>3</sup> (62.4 pcf), with that of the prototype being 1,027 kg/m<sup>3</sup> (64 pcf). The specific weights of the model material used for construction differed for the prototype; therefore, the Hudson (1975) transference equation was used to determine model material weights as follows:

$$\frac{(W_a)_m}{(W_a)_p} = \frac{(\gamma_a)_m}{(\gamma_a)_p} \left(\frac{l_m}{l_p}\right)^3 \left[\frac{(S_a)_p - 1}{(S_a)_m - 1}\right]^3$$
 (1)

in which the subscripts m and p refer to model and prototype quantities, respectively, with

 $W_a$  = weight of individual armor unit

 $\gamma_a$  = specific weight of an individual armor unit

 $l_m/l_p$  = linear scale of the model

 $S_a$  = the specific gravity of an individual armor unit relative to the water in which it is placed,  $S_a = \gamma_a / \gamma_w$ 

 $\gamma_w$  = specific weight of water

When constructing all small-scale physical models of rubble mounds, scale effects of viscous forces associated with flow through the underlayers and core of the structure are of concern. In the reproduction of prototype conditions, the model materials need to be properly sized to avoid Reynolds and other scale effects. Selected scaling was based on available armor sizes and checked for scale effects following the methods put forth by Keulegan (1973). The geometrically scaled underlayer size was found to be satisfactory. The core size, scaled from limited information on the true prototype condition, was modeled using coarse sand. This sizing allows for a conservative design with no transmission and maximum reflection. Sizes of prototype and model breakwater armor and underlayer materials are listed in Table 2.

Table 2 Prototype and Model Material Sizes				
	Prototype	Model		
Armor Type	Tribar 4.1 tonnes (4.5 U.S. tons)	Tribar 285.8 g (0.63 lb)		
Underlayer, W,	30% Porosity block 1.45 tonnes (1.6 U.S. tons)	30% Porosity block 105.7 g (0.233 lb)		
Underlayer,W <sub>2</sub>	Stone 91 - 182 kg (200-400 lb)	Stone 11.3 g (0.025 lb)		
Underlayer,W <sub>3</sub>	Stone 0.45 - 45 kg (1-100 lb)	Stone 1.8 g (0.004 lb)		
Core,W <sub>4</sub>	Coral Dredged Material < 0 .45 kg (1 lb)	Coarse sand D <sub>50</sub> = 2 mm (0.08 in)		

#### **Test Facilities and Equipment**

Tests were conducted in a 47.2-m-long, 0.6-m-wide, 1.8-m-deep wave tank. Figure 1 shows tank dimensions, bottom slopes, wave gauge placement, and structure location for stability tests. The 1V:20H seaward slope transitioned to a flat reef, using a 1V:1H slope, to represent local bathymetry seaward of the breakwater location. The structure was located at a prototype shoreward distance of 37 m (120 ft) from the crown of the reef. The prototype water depth at the toe of the structure was 3.9 m (12.9 ft).

Waves were generated by a hinge-type electronically controlled hydraulic wavemaker. Displacement of the wave board was controlled by a command signal transmitted to the wave board by a Digital Equipment Corporation MicroVax II computer. Waves were produced by the periodic displacement of the wave board. Regular wave signals were produced by a synthesized function generator, which can generate sine waves. Several random wave tests were conducted where command signals to drive the wave board were generated to simulate a Texel Marsen Arsloe (TMA) shallow-water spectrum (Hughes 1984) for several wave periods.

#### **Breakwater Test Section**

The configuration of the modeled 2-D cross section (Figure 2) simulated a representative prototype section of the reach between Sta. 4+00 and 6+72 (Figure 3). The breakwater cross section consists of a typical trapezoidal geometry. Tribars are used to armor both the sea side and lee side of the structure (Figure 4). They lay atop the first underlayer, specially fabricated concrete 30-percent porosity blocks. The second and third stone underlayers protect the coral dredged material core. The structure is capped with a concrete rib cap typical of many POD concrete armored structures.

A major task during this modeling effort was the construction of the 30-percent porosity blocks (Figure 5) used in place of underlayer stone. In order to remain on schedule and expedite the effort, the blocks were modeled using oak ballasted with lead. Using this method, the geometry, weight, and weight density were satisfactorily modeled at a 1:23 scale, achieving a scaled prototype weight of 1.45 tonnes (1.6 U.S. tons), and a weight density of 2,246 kg/m³ (140 pcf). For the blocks, the mean unit weight tolerance was within 4 percent of the target weight of 105.7 g (0.233 lb) with a standard deviation of ±3 percent.

The materials used for the core and stone underlayers were placed by hand, smoothed to grade, and compacted with hand trowels to simulate consolidation that would have occurred due to wave action. The 30-percent porosity blocks and tribar armor layer were then placed on the structure. The rib cap (Figure 6) was constructed at a 1:23 geometric scale. This was secured to tie-downs placed in the model base to prevent movement.




Figure 1. Flume layout




Figure 2. Breakwater configuration




Figure 3. Ofu breakwater alignment between Sta. 4+00 and Sta. 6+72




Figure 4. 4.1-tonne tribar




Figure 5. Thirty-percent porosity block used for underlayer




Figure 6. Rib cap configuration for Ofu breakwater

# 3 Test Results

#### **Data Acquisition**

Water surface elevations were recorded by single wire capacitance-type gauges with a sampling rate of 20 samples/sec. Nine gauges were used during calibration of the flume and during stability tests. Array 1 was placed 10 m (30 ft) offshore of the reef to obtain offshore wave heights, and the remaining gauges were placed on the reef, fronting the structure such that they could be arranged in arrays of three gauges each (Figure 1). This permitted calculation of incident and reflected wave heights by the method of Goda and Suzuki (1976). Data were stored on a MicroVax II minicomputer and analyzed using the Time Series Analysis computer program (Long and Ward 1987), which can execute several analysis operations.

Operations used for monochromatic wave tests were mean downcrossing analysis to obtain significant wave heights  $H_s$ , and maximum wave heights  $H_{max}$ , significant and average wave periods, and mean water levels at each gauge. For random waves, single-channel frequency domain analysis was used to acquire peak period  $T_p$ , zero-moment wave height  $H_{mo}$ , and spectral density plots for each gauge. Unidirectional spectral density incident/reflection analysis was used to determine incident and reflected wave heights at each array.

# Calibration/Test Conditions/Wave Height Determination

The wave generator was calibrated for both monochromatic and random waves without the breakwater in place. A three-gauge array was positioned offshore. To determine wave heights on the reef, a second array was placed at the toe of the breakwater. The calibration was for several wave periods and heights, windowing the 17-sec, 3.47-m (11.4-ft) prototype design wave condition at a prototype water depth of 3.9 m (12.9 ft) at the breakwater toe. Calibration runs provided a baseline of attainable wave heights for each wave period.

Calibration also allowed a comparison between offshore wave height and wave heights on the reef prior to placing the structure. Using the two Goda arrays during the initial calibration and a single offshore array and six single wave gauges on the reef once the structure was in place permitted calculation of reflection coefficients for the reef and structure.

While the scope of work requested testing with only monochromatic waves for a design wave period of 17 sec and wave height of 3.47 m (11.4 ft, if it could be obtained at the specified water depth of 3.9 m), the author felt it prudent to establish the most severe breaking wave conditions, for a range of selected periods that may break on the structure.

Figures 7-13 show significant monochromatic wave heights attained during calibration runs, both offshore and on the reef at the toe of the structure. In general, the shorter period waves ( $\leq 15$  sec) tended to shoal more quickly and break nearer the edge of the reef. For longer period waves (15-18 sec), the wave would shoal and break in the vicinity of the location where the structure would be placed. The 20-sec wave period was limited by the wave generator stroke and did not break near the structure location proposed.




Figure 7. Wave heights as a function of board stroke, T = 9 sec




Figure 8. Wave heights as a function of board stroke, T = 11 sec




Figure 9. Wave heights as a function of board stroke, T = 13 sec




Figure 10. Wave heights as a function of board stroke, T = 15 sec




Figure 11. Wave heights as a function of board stroke, T = 17 sec




Figure 12. Wave heights as a function of board stroke, T = 18 sec




Figure 13. Wave heights as a function of board stroke, T = 20 sec

During calibration without the structure, the most energetic and maximum achievable wave was the 18-sec wave, with a significant wave height  $H_s$  at the proposed structure toe of 3.9 m (12.8 ft). For the 17-sec design wave,  $H_s$  at the proposed toe was 3.7 m (12.1 ft). This wave broke either just seaward or at the location where the structure would be located. With the structure in place on the reef, the suite of wave conditions was rerun. Figure 14 shows the effects of wave period on the maximum attainable wave height at the structure toe, both with and without the structure in place. Figures 15-18 compare maximum wave heights across the reef, both with and without the structure in place. In general, the presence of the structure tended to attenuate wave height in front of the structure.

Table 3 summarizes the maximum wave conditions attained with the structure in place and used for the 2-D stability test.

Wave Type	Water Depth m, (ft)	Wave Period sec	H <sub>e</sub> - Offshore m, (ft)	H <sub>a</sub> - at Structur m, (ft)
Regular	3.9 (12.8)	20	2.6 (8.5)	2.8 (9.2)
Regular	3.9 (12.8)	18	4.2 (13.8)	3.9 (12.8)
Regular	3.9 (12.8)	17	3.6 (11.8)	3.7 (12.1)
Regular	3.9 (12.8)	15	4.0 (13.1)	3.0 (9.8)
Regular	3.9 (12.8)	13	4.3 (14.1)	3.2 (10.5)
Regular	3.9 (12.8)	11	6.1 (20.0)	3.9¹ (12.8)
Regular ·	3.9 (12.8)	. 9	8.1 (26.6)	4.0¹ (13.1)
irregular	3.9 (12.8)	7.2	1.42 (4.6)	1.5² (4.9)
Irregular	3.9 (12.8)	12	1.42 (4.6)	1.5 <sup>2</sup> (4.9)

<sup>1</sup> These waves broke on reef, not on structure.

<sup>&</sup>lt;sup>2</sup> H<sub>mo</sub> wave height.




Figure 14. Maximum attainable wave height on reef at structure toe




Figure 15. Wave transformation on reef for T = 15 sec




Figure 16. Wave transformation on reef for T = 17 sec




Figure 17. Wave transformation on reef for T = 18 sec




Figure 18. Wave transformation on reef for T = 20 sec

#### Test Procedures

It was agreed by both POD and WES that a single cross section would be tested at a single water level for one monochromatic design wave condition.

Photographs and video were taken prior to testing, during calibration, and during the stability tests. Upon completion of construction of the structure, the tank was flooded to the appropriate depth and the structure was exposed to several cycles of low-level waves. These initial wave runs allowed simulation of the settling and nesting of the newly constructed section which would occur under typical daily wave conditions prior to being exposed to a design level storm. After the structure was exposed to low-level waves, the test wave conditions listed in Table 3 were generated. Prototype duration for each wave height was 14 min (180 sec model). Test durations were completed, subjecting the structure to over 2,000 monochromatic waves of varying periods. The procedure of testing in bursts for regular waves prevented contamination of incident waves by waves re-reflected from the wave generator. Upon completion of a cycle, sufficient time was provided for the water surface to settle, and the still-water level was verified before the next cycle began.

The response of the structure, and the location and severity of the breaking waves to each cycle of test waves were recorded. Detailed model observation included movement of units on the structure and a general statement of the overall stability of the structure. The armor slope was reconstructed twice.

The purpose of the repeat test was to determine the presence of any uncontrolled variations in model construction technique that might affect stability of the structure.

At the conclusion of the tests, the tank was drained and the condition of the structure was summarized in test notes and documented with photographs. Photographs taken during the study are shown in Appendix A.

#### **Reporting Model Observations**

The structure was visually inspected during and after testing and results were recorded on log sheets. The main objective of the test series was to check for any instability in the selected tribar armor layer. The stability of the test sections could be calculated from the test results using the following formula:

$$K_d = \frac{\gamma_a H^3}{W_a (S_a - 1)^3 \cot \theta} \tag{2}$$

where

 $K_d$  = Hudson stability coefficient

H = wave height at the structure that causes no damage, i.e., wave height at which damage is less than or equal to 2 percent of the number of primary armor units placed on the respective breakwater slope

 $\Theta$  = angle of the structure slope measured from horizontal

 $W_a$  = weight of an individual armor unit

 $\gamma_a$  = weight density of the armor unit

 $S_a$  = specific gravity of the armor unit

In the present study, the design wave height at the structure toe was used to calculate stability coefficients for monochromatic waves.

# **Summary of Two-Dimensional Stability Tests**

The two-dimensional stability tests are summarized in Table 4.

Table 4					
Summary	Of 2-D	<b>Stability</b>	Tests for	r 4.1-tonne	<b>Tribars</b>

Wave Period (sec)	Wave Height m,(ft)	K <sub>d</sub>	Observations	
20.0	2.8 (9.2)	4.2	No movement on slope	
18.0	3.9 (12.8)	11.3	Maximum of two units rocking on slope	
17.0	3.7 (12.1)	9.5	Only one unit rocking intermittently	
15.0	3.0 (9.8)	5.1	No movement	
13.0	3.2 (10.5)	6.2	No movement	
11.0	3.9 <sup>1</sup> (12.8)	- 11.3	No movement	
9.0	4.0¹ (13.1)	12.1	No movement	
7.2 <sup>2</sup>	1.5 <sup>1</sup> (4.9)	>1.0	No movement	
12²	1.5¹ (4.9)	>1.0	No movement	

<sup>&</sup>lt;sup>1</sup> Waves breaking on reef.

<sup>&</sup>lt;sup>2</sup> Random waves.

# 4 Conclusions and Comments

The physical model investigation of the 1:23 scale Ofu breakwater section indicates that the 4.1-tonne (4.5-ton) tribar primary armor layer will remain hydraulically stable for the specified design wave condition (17 sec, 3.47 m (11.4 ft)) using a first underlayer of 1.45-tonne (1.6-ton) 30-percent porosity blocks laid flat on the slope. In addition, the most severe breaking waves that could be made to break on the structure were reproduced for wave periods from 9 to 20 sec. For any of the wave conditions tested, only mild rocking of a few units was observed.

While the test series indicates that units will remain hydraulically stable, several observations were made and the author feels it necessary to express his opinion as qualifying statements:

- a. This was only a 2-D test that checked hydraulic stability of uniformly placed tribars atop an underlayer of uniformly placed manmade concrete 30-percent porosity blocks. Tests were for primarily one design wave condition, one water depth, and one localized bathymetry. No conclusions can be drawn for units subject to multi-directional waves (head sections), stability at lateral or longitudinal transitions, larger wave loadings (typhoon conditions), changes in water depth (extreme tidal ±, storm surge, etc.), or changes in structure geometry and/or elevations.
- b. Structural integrity of the 1.45-tonne (1.6-ton) unreinforced concrete block was not addressed in this study. The possibility exists that the reduction in cross-sectional area necessary to introduce porosity for overall hydraulic stability, may be detrimental to the structural strength of the block, especially if loading from overlying tribar movement or "pumping" is initiated by sustained wave attack. Care must be taken in the placement of these blocks and the tribars so as not to allow impact due to rough handling. Construction quality control must be maintained in both the casting and placement.
- c. No structural guidance is available to the Corps for tribars; however, much research has been done on dolosse (another slender unit). For similar size dolosse with similar central section dimensions, a minimum concrete strength f'c = 35 Mpa (5,000 psi) (mean minus one standard

deviation) would be specified. This assumes no impact loading. Unit-to-unit impact loading must be avoided both during placement and during service life. If units are broken during placement, they must be removed and replaced with intact units. This is especially important on "laid-up" armor, which is more susceptible to unraveling than randomly placed armor, once damage is initiated.

d. Care must be taken to get a tight packing on slope, and to assure secure transition zones, meaning toe units must be well-entrenched, lateral transitions buttressed, and crown units secured by the rib cap.

# References

- Goda, T., and Suzuki, Y. (1976). "Estimation of incident and reflected waves in random wave experiments." *Proc. of the 15th Coastal Engrg. Conf.* Honolulu, Hawaii, 828-845.
- Hudson, R.Y. (1975). "Reliability of rubble-mound breakwater stability models," Miscellaneous Paper H-75-5, U.S. Army Engineer Waterways Experiment Station, Vicksburg, MS.
- Hughes, S.A. (1984). "The TMA shallow-water spectrum description and applications," Technical Report CERC-84-7, U.S. Army Engineer Waterways Experiment Station, Vicksburg, MS.
- Keulegan, G.H. (1973). "Wave transmission through rock structures; hydraulic model investigation," Research Report H-73-1, U.S. Army Engineer Waterways Experiment Station, Vicksburg, MS.
- Long, C.E., and Ward, D.L. (1987). "Time series analysis," unpublished computer program, U.S. Army Engineer Waterways Experiment Station, Vicksburg, MS.
- Stevens, J.C., Bardsley, C.E., Lane, E.W., and Straub, L.G. (1942). "Hydraulic models." Manuals on engineering practice No. 25. American Society of Civil Engineers, New York.

# Appendix A Photographs of Ofu Breakwater 2-D Stability Tests




Figure A1. Model of Ofu breakwater




Figure A2. Trough of short-period wave (T = 9 sec) passing over reef




Figure A3. Short-period wave (T = 11 sec) breaking on reef




Figure A4. Wave (T = 17 sec) breaking on structure




Figure A5. Wave (T = 18 sec) breaking on structure

#### REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC20503.

OF REPORT OF THIS PAGE OF ABSTRACT	1.	AGENCY USE ONLY (Leave blank)	2. REPORT DATE October 1995	3. REPORT TYPE AND DATES COVERED Final report			
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army Engineer Waterways Experiment Station 3909 Halls Ferry Road, Vicksburg, MS 39180-6199  9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) U.S. Army Engineer Division, Pacific Ocean Pt. Shafter, HI 96858-5440  10. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) U.S. Army Engineer Division, Pacific Ocean Pt. Shafter, HI 96858-5440  11. SUPPLEMENTARY NOTES Available from National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161.  12a. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution is unlimited.  13. ABSTRACT (Maximum 200 words) This report describes a two-dimensional physical model investigation of the Ofto breakwater, American Samoa. Two-dimensional wave tests were conducted to determine the stability of selected concrete armor units when placed on concrete revertment blocks and subjected to a design condition of a 17-sec, 3.47-m (11.4-ft) wave. A proposed breakwater consisted of 4.1-tonne (1.6-V.Ston) inbar armor units, placed on an underlayer of 1.45-tonne (1.6-V.Ston) 30-percent porosity blocks, secured at the crown transition with a concrete rib cap. Testing indicated that units will remain hydraulically stable for the specified design wave condition.  14. SUBJECT TERMS Concrete armor units Of breakwater Two-dimensional wave tests Two-dimensional wave tests Of breakwater Two-dimensional wave tests Of BRITACT  15. NUMBER OF PAGES 36 16. PRICE CODE  17. SECURITY CLASSIFICATION OF ABSTRACT  20. LIMITATION OF ABSTRACT	4.		FUNDING NUMBERS				
U.S. Army Engineer Waterways Experiment Station 3909 Halls Ferry Road, Vicksburg, MS 39180-6199  9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) U.S. Army Engineer Division, Pacific Ocean Ft. Shafter, HI 96858-5440  10. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) U.S. Army Engineer Division, Pacific Ocean Ft. Shafter, HI 96858-5440  11. SUPPLEMENTARY NOTES Available from National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161.  12a. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution is unlimited.  13. ABSTRACT (Maximum 200 words) This report describes a two-dimensional physical model investigation of the Ofu breakwater, American Samoa. Two-dimensional wave tests were conducted to determine the stability of selected concrete armor units when placed on concrete revetment blocks and subjected to a design condition of a 17-sec, 3.47-m (11.4-ft) wave. A proposed breakwater consisted of 4.1-tonne (4.5-U.Ston) tribar armor units, placed on an underlayer of 1.45-tonne (1.6-U.Ston) 30-percent porosity blocks, secured at the crown transition with a concrete rib cap. Testing indicated that units will remain hydraulically stable for the specified design wave condition.  14. SUBJECT TERMS Concrete armor units Of the Deskwater Of United Maximum 200 wave tests Offu breakwater Offu Harbor  15. NUMBER OF PAGES 36 16. PRICE CODE  17. SECURITY CLASSIFICATION OF ABSTRACT  18. SECURITY CLASSIFICATION OF ABSTRACT	6.						
U.S. Army Engineer Division, Pacific Ocean Ft. Shafter, HI 96858-5440  11. SUPPLEMENTARY NOTES Available from National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161.  12a. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution is unlimited.  12b. DISTRIBUTION CODE  13. ABSTRACT (Maximum 200 words) This report describes a two-dimensional physical model investigation of the Ofu breakwater, American Samoa. Two-dimensional wave tests were conducted to determine the stability of selected concrete armor units when placed on concrete revertment blocks and subjected to a design condition of a 17-sec, 3.47-m (11.4-ft) wave. A proposed breakwater consisted of 4.1-tonne (4.5-U.Ston) tribar armor units, placed on an underlayer of 1.45-tonne (1.6-U.Ston) 30-percent porosity blocks, secured at the crown transition with a concrete rib cap. Testing indicated that units will remain hydraulically stable for the specified design wave condition.  14. SUBJECT TERMS Concrete armor units Of Ureakwater Of U Harbor  15. NUMBER OF PAGES 36 16. PRICE CODE  17. SECURITY CLASSIFICATION OF THIS PAGE  19. SECURITY CLASSIFICATION OF ABSTRACT	7.	U.S. Army Engineer Waterways Ex	REPORT NUMBER				
Available from National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161.  12a. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution is unlimited.  13. ABSTRACT (Maximum 200 words)  This report describes a two-dimensional physical model investigation of the Ofu breakwater, American Samoa. Two-dimensional wave tests were conducted to determine the stability of selected concrete armor units when placed on concrete revetment blocks and subjected to a design condition of a 17-sec, 3.47-m (11.4-ft) wave. A proposed breakwater consisted of 4.1-tonne (4.5-U.Ston) tribar armor units, placed on an underlayer of 1.45-tonne (1.6-U.Ston) 30-percent porosity blocks, secured at the crown transition with a concrete rib cap. Testing indicated that units will remain hydraulically stable for the specified design wave condition.  14. SUBJECT TERMS Concrete armor units Of ubreakwater Of u		U.S. Army Engineer Division, Paci					
Approved for public release; distribution is unlimited.  13. ABSTRACT (Maximum 200 words)  This report describes a two-dimensional physical model investigation of the Ofu breakwater, American Samoa.  Two-dimensional wave tests were conducted to determine the stability of selected concrete armor units when placed on concrete revetment blocks and subjected to a design condition of a 17-sec, 3.47-m (11.4-ft) wave. A proposed breakwater consisted of 4.1-tonne (4.5-U.Ston) tribar armor units, placed on an underlayer of 1.45-tonne (1.6-U.Ston) 30-percent porosity blocks, secured at the crown transition with a concrete rib cap. Testing indicated that units will remain hydraulically stable for the specified design wave condition.  14. SUBJECT TERMS  Concrete armor units  Concrete armor units  Porosity blocks  Of breakwater  Two-dimensional wave tests  Of Uharbor  15. NUMBER OF PAGES  36  16. PRICE CODE  17. SECURITY CLASSIFICATION OF THIS PAGE  19. SECURITY CLASSIFICATION OF ABSTRACT	11.		al Information Service, 5285	Port Royal Road, Springfield	1, VA 22161.		
This report describes a two-dimensional physical model investigation of the Ofu breakwater, American Samoa.  Two-dimensional wave tests were conducted to determine the stability of selected concrete armor units when placed on concrete revetment blocks and subjected to a design condition of a 17-sec, 3.47-m (11.4-ft) wave. A proposed breakwater consisted of 4.1-tonne (4.5-U.Ston) tribar armor units, placed on an underlayer of 1.45-tonne (1.6-U.Ston) 30-percent porosity blocks, secured at the crown transition with a concrete rib cap. Testing indicated that units will remain hydraulically stable for the specified design wave condition.  14. SUBJECT TERMS  Concrete armor units  Of breakwater  Two-dimensional wave tests  Ofu Harbor  15. NUMBER OF PAGES  36  16. PRICE CODE  17. SECURITY CLASSIFICATION OF ABSTRACT  19. SECURITY CLASSIFICATION OF ABSTRACT	12a			12b.	DISTRIBUTION CODE		
Concrete armor units Ofu breakwater Ofu Harbor  16. PRICE CODE  17. SECURITY CLASSIFICATION OF REPORT  18. SECURITY CLASSIFICATION OF THIS PAGE  19. SECURITY CLASSIFICATION OF ABSTRACT  20. LIMITATION OF ABSTRACT	13.	This report describes a two-dim Two-dimensional wave tests were concrete revetment blocks and sub consisted of 4.1-tonne (4.5-U.Sto porosity blocks, secured at the crow	conducted to determine the sojected to a design condition of on) tribar armor units, placed own transition with a concrete	tability of selected concrete a of a 17-sec, 3.47-m (11.4-ft) on an underlayer of 1.45-ton	armor units when placed on wave. A proposed breakwater ne (1.6-U.Ston) 30-percent		
Concrete armor units Porosity blocks Ofu breakwater Two-dimensional wave tests Ofu Harbor  16. PRICE CODE  17. SECURITY CLASSIFICATION OF THIS PAGE 19. SECURITY CLASSIFICATION OF ABSTRACT							
OF REPORT OF THIS PAGE OF ABSTRACT	14.	Concrete armor units Porosit Ofu breakwater Two-di	-		36		
	17.	OF REPORT C			ION 20. LIMITATION OF ABSTRACT		